



G008 - What is the correct way to rate a sling with a factor of safety of 5:1 if the master link is rated at 4:1 and the rope at 5:1?

It is the WLL of the product that matters, the sling assembler does not need to worry about the working coefficients providing that they select the correct component to the correct standard and that the WLL's of all items in the sling are the same or greater than the intended sling WLL.

Please note: The content of the guidance in these frequently asked questions is provided for general information only. Whilst they are intended to represent a standard of good practice, they have no legal status and compliance with them does not exempt you from compliance with any legal requirements. Although we make reasonable efforts to provide accurate guidance, we make no representations, warranties or guarantees, whether express or implied, that the content of the guidance given in these frequently asked questions and our interpretation of the requirements given is accurate, complete or up-to-date. It is therefore responsibility of those with specific duties under the legislation to ensure that they fulfil the obligations imposed on them.

Lifting Equipment Engineers Association

3 Osprey Court
Hinchbrook Business Park
Huntingdon PE29 6FN
United Kingdom

Tel: +44 (0) 1480 432801 • Email: mail@leeaint.com